Attorney Docket No. 725.1154C

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yukihiro MORIYAMA

Application No.: 10/667,858

Confirmation No.: 1390

Filed: September 23, 2003

U.S. Patent No.: 6,779,831 82

Issued: August 20, 2004

For: DOOR STRUCTURE FOR VEHICLE

ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Batch No.:

Certificate

MAR 0 7 2005

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the applicant; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

03/03/2005 RMEBRAH1 00000151 6779831

01 FC:1811

100.00 OP

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501 Respectfully submitted,

STAAS & HALSEY LLP

David M. Pi

Registration No. 25,908

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,779,831/82

DATED: August 20, 2004

INVENTOR(S): Yukihiro MORIYAMA

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 14,

line 4, delete "is located" (second occurrence).

Column 15,

line 12, change "pilled" to --pulled --.

Column 16.

line 45, (claim 6, line 7) change "sate" to --state--

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Avenue, N.W. Suite 700 Washington, DC 20005

PATENT NO. 6,779,831

No. of add'l copies @ 304 per page Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,779,831 12

DATED: August 20, 2004

INVENTOR(S): Yukihiro MORIYAMA

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 14,

معلاه ريس

line 4, delete "is located" (second occurrence).

Column 15.

line 12, change "pilled" to --pulled --.

Column 16,

line 45, (claim 6, line 7) change "sate" to --state--

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Avenue, N.W. Suite 700 Washington, DC 20005

PATENT NO. 6,779,831

No. of add'l copies @ 304 per page